



GENERAL OFFICES • 3M CENTER • SAINT PAUL, MINNESOTA 55101 • TEL. (612) 733-1110

Mincom Division

To Our Customers:

In the past, some M-79 owners have notified us of a high incidence of mechanical and/or brush noise coming from the capstan motor assembly in their recorders.

We have consequently re-engineered these assemblies using new style brushes and bearings. We have also modified the motor housing to preclude any possibility of audible motor noise.

To further improve the noise rejection and to realize the utmost benefit from the above changes, the procedures and modifications called for on the attached Field Service Bulletin should be incorporated.

All new M-79 recorders are being shipped with these modifications incorporated.



MINNESOTA MINING AND MANUFACTURING COMPANY